**Products** 



## **Cable or Bar Primary Current Transformers LSERIES**



- Primary current from 50A to 4800A
- For bus bars 20,25,30,40,50,60,80 or 100 mm wide
- For cable diameter up to Ø 60 mm
- Terminal cover as standard for enhanced safety

Moulded case current transformers for the measurement of AC currents from 50A to 4800A.

They are made of a non-flammable plastic material. This new range of current transformers has been designed for an easy installation: all transformers can be delivered with DIN rail clips. They are equipped as standard with a sealable terminal cover to comply with the most demanding safety requirements. This range include current transformers for measuring duties and is suitable for every simple application.

Technical data			
Highest voltage for equipment	750 V		
power-frequency withstand voltage	3000 V		
primary current Ipn	50 to 4800A		
secondary current Isn	5 or 1A		
Frequency	50 or 60 Hz		
Rated output	1 to 15 VA		
Accuracy class	0.5 - 1 - 3		
Security factor	5 to 30		
Continuous thermal current	1.2 lpn		
short-time thermal current Ith	80 lpn . 1s or 80 lpn.1s		
Dynamic current Idyn	2.5lth		
Insulation class	A		
Altitude	1000 m		
	-5C° to + 40 C°		
Let Make Wildlife	-25C° to + 40 C°		
Ambient temperature	-40C° to + 40 C°		
tandards IEC60044-1, IEC61869-2,ANSI C57.13			

Other characteristics on request	
Highest voltage for equipment	Up to 1200 V
power-frequency withstand voltage	Up to 6 KV
secondary current Isn	0.01 to 0.5 A
Frequency	1 to 10000 Hz
Continues thermal current	1.2 to 1.5Ipn and 2Ipn
Ambient temperature	-40C° to + 70 C°
Standard	ANSI C57.13 - CAN3 C13 - AS 1675


\*This document is the property of Pars Shar and maybe changed without prior notice\*


contact us:	info@parsshar.com		
Tel:	021-22911553 to 5		
Fax:	021-22263225		




## L SERIES


selection table						
Ip	Туре		Output			
A		Ma	aximum	VA		
		cl3	cl1	Cl0.5		
50	L3A	1				
	L4A	1.25				
60	L3A	1.25				
	L4A	2.5				
75	L3A	2.5				
	L4A	2.5				
100	L3A	3.75	2.5			
	L4A	3.75	2.5			
125	L3A	3.75	2.5			
	L4A	3.75	2.5			
150	L3A	5	3.75	2.5		
	L4A	5	3.75	2.5		
200	L3A	5	3.75	2.5		
	L4A	7.5	5	2.5		
250	L3A	10	7.5	5		
	L4A	10	7.5	5		
300	L3A	10	7.5	7.5		
	L4A	15	7.5	5		
400	L3A	15	10	10		
	L4A	15	15	10		
500	L3A	15	15	15		
	L4A	15	15	10		
600	L3A	15	15	15		
	L4A	15	15	10		
750	L4A	15	15	15		
1000	L4A	15	15	15		





## L4A





\*This document is the property of Pars Shar and maybe changed without prior notice\*